

# Osland Piping Supply

## Copper Fabrication & Carts



The primary goals for Grooved, Sweat, or G-PRESS Copper Fabrication are:

- Minimize loose pieces - Fabricate in a controlled Fab Shop environment with significantly higher productivity compared to the field.
- Control & Minimize material handling costs at the jobsite
- Better theft control - Product is not shipped to the jobsite until it is ready to install - Less chance for material to disappear
- Less scrap at jobsite - easier to recycle / repurpose at the Fab Shop
- Specialized carts which reduce installation time & labor on the jobsite.

Pre-planning is essential for fabrication to be effective. It is important to identify what areas or systems should be pre-fabricated and how the fabrication should be presented to the jobsite; bulk, or in carts (several sizes, types & styles).